



GE CLUTCH

Spring Chart

SPRING NO.	SPRING COLOR	LIGHT SHOES ENGAGEMENT	HEAVY SHOES ENGAGEMENT
NA-K017	Black	2100 rpm	1820 rpm
NA-K020	Red	2450 rpm	1950 rpm
NA-K030	White	2740 rpm	2420 rpm
NA-K040	Blue	2960 rpm	2530 rpm
NA-K050	Purple	3010 rpm	2575 rpm
NA-K060	Green	3440 rpm	2975 rpm
NA-K079	Orange	3660 rpm	3100 rpm
NA-K086	Big Brown	4020 rpm	3380 rpm
NA-K088	Big Red	4320 rpm	3530 rpm